Owner Name and Address: Swallows Garage 114 Main St PO Box 63 Martinsdale MT 59053 Phone: (406) 572-3615

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3000665	Swallows Garage	114 Main St	Martinsdale	59053	(406) 572-3615

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 02 Currently In Use	3929	4/2/1985 21 / No	Diesel 560	STI-P3 None	Galvanized Steel Cathodically Protected	Safe Suction	<pre>BCDEFGHIJKL B DEFGHI•KL</pre>	Yes Yes Yes Yes
5 / 01 Currently In Use	3930	4/2/1985 21 / No	Gasoline 560	STI-P3 None	Galvanized Steel Cathodically Protected	Safe Suction	● B C D E F G H () Ø LB D E F G H () ● Ø L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 1 of 5

Owner Name and Address: Van Oil Co PO Box E White Sulphur Springs MT 59645 Phone: (406) 547-3636

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3000478	Van Oil Co 12 W Main St	12 W Main St	White Sulphur Spring	59645	(406) 547-9998

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
5 / 06 Currently in Use	2211	6/6/1991 15 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL O OEFGHIJKL	Yes Yes Yes Yes
7 / 07 Currently in Use	2212	6/6/1991 15 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABC●EFGHIJ&L ● ●EFGHIJ&L	Yes Yes Yes Yes
8 / 08 Currently in Use	2213	6/6/1991 15 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL O OEFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 2 of 5

Owner Name and Address: White Sulphur Springs School Dist 8 2090 Central Ave S PO Box C White Sulphur Springs MT 59645 Phone: (406) 547-335

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
3004720	White Sulphur Springs School Dist 8	209 Central Ave S	White Sulphur Spring	59645	(406) 547-3351	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
6 / S6 Currently In Use	2261	8/1/1998 07 / No	Heating Oil 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Safe Suction	8 DEF@HIJKL	Yes Yes Yes Yes
7 / S7 Currently In Use	2262	8/1/1998 07 / No	Heating Oil 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Safe Suction	8 DEF 0 H 1 J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 3 of 5

Owner Name and Address: Berg Garage Inc PO Box 470 White Sulphur Springs MT 59645 Phone: (406) 547-3514

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
3007694	Berg Garage Inc	11 W Main St	White Sulphur Spring	59645	(406) 547-3514	•

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently in Use	434	1/1/1990 16 / No	Gasoline 500	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	B C D E F G H () K LB D E F G H () € K L	Yes Yes Yes Yes
4 / 04 Currently in Use	435	1/1/1990 16 / No	Gasoline 500	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	B DEFGHIJKU B DEFGHIJKU	Yes Yes Yes Yes
5 / 05 Currently in Use	436	1/1/1990 16 / No	Gasoline 500	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	B © D E F G H () Ø LB D E F G H () Ø Ø L	Yes Yes Yes Yes
6 / 06 Currently in Use	437	1/1/1990 16 / No	Diesel 500	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	B © D E F G H () Ø LB D E F G H () Ø Ø L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 4 of 5

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
3008724	Town Pump Inc White Sulphur Springs M	215 Main St	White Sulphur Spring	59645	(406) 547-3310	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 01 Currently in Use	2533	5/10/1972 34 / No	Gasoline 12,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	(ABC • E F G H J K L) (• • E F G H J K L)	Yes Yes Yes Yes
3 / 02 Currently in Use	2534	5/10/1972 34 / No	Gasoline 6,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH)JKU (DEFGH)JKU	Yes Yes Yes Yes
4 / 03 Currently in Use	2535	5/10/1980 26 / No	Gasoline 12,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH))(KL) (OEFGH))(KL)	Yes Yes Yes Yes
5 / 04 Currently in Use	2536	5/10/1989 17 / No	Gasoline 10,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes
6 / 05 Currently in Use	2537	10/1/1992 13 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABCOEFGHIJKL</pre>	Yes Yes Yes Yes
7 / 07 Currently In Use	4119	9/1/1999 06 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABC•EF•H1J&L B•EF•H1J&L	Yes Yes Yes Yes
8 / 08 Currently In Use	4120	9/1/1999 06 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B OEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 5 of 5